

IMPORTANT SAFETY NOTICE

Recall of Salewa Alp Trainer 2 Mid GTX Hiking Boots – U.S. & Canada

Men's and Women's models of the Salewa Alp Trainer 2 Mid GTX Hiking Boots manufactured through March 2022 are recalled. Boots manufactured in April 2022 and later are not subject to recall.


Recalled AT2 Boot Photo



The recalled Men's Alp Trainer 2 Mid GTX Boots, model number 00-0000061382, were manufactured in three color options: black/black, raw green/pale frog, and walnut/fluo orange. The recalled Women's Alp Trainer 2 Mid GTX Boots, model number 00-0000061383, were manufactured in two color options: black/black, and duck green/rhododendron.

Recalled AT2 Boots can be identified by the production date on the inside of the tongue label of the boot. The production date on the label starts with an "FS". The first number on the label is the last number of the year of production and the second number designates the month of production. Thus, e.g., FS 2-04 designates a production date of April 2022.

All AT2 Boots with production dates FS 1-xx, FS 2-01, FS 2-02, and FS 2-03 are subject to recall. For AT2 Boots with production date FS 2-04, only Men's AT2 Boots in black/black are subject to recall. All AT2 Boots with production dates starting with FS 2-04 and later (e.g., FS 2-05, 2-06, etc.) are not subject recall (except as to Men's AT2 Boots in black/black) (the "Fall 22 AT2 Boots").



Fall 22 AT2 Boot Photo *not subject to recall*



The Fall 22 AT2 Boots can be distinguished from the Recalled AT2 Boots by examining the sides of the boots: the Fall 22 AT2 Boots have a covered cable and different lacing point (15mm or 1.5 cm closer to the tongue) than the Recalled AT2 Boots.

Hazard: If the Recalled AT2 Boots are laced loosely or untied, unlaced at the ankle support of the boot, not laced through the eyelet, or the lace hooks are left unlaced, etc., it is unlikely but possible that the lace hook on the inside of one boot can catch on a loose cable on the inside of the other boot, posing a tripping and/or fall hazard and risk of injury to the consumer.

Consumers should immediately cease using Recalled AT2 Boots and return them as soon as possible to Salewa for replacement. Please contact Salewa toll-free at 844-412-7013 from 9 a.m. to 5 p.m. MT Monday through Friday, email at AlpTrainer2@salewa.com or online at www.salewa.com/en-us/ and click on “Alp Trainer 2 Mid GTX Voluntary Recall” for more information.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission and Health Canada.